

Using Makerspace version of VCarve Pro at the Guild

After completing your design on your Client copy of VCarve Pro you will need to bring your design to the Guild on a USB Drive and download your program to the Guilds Master Copy of VCarve Pro to generate the G-Code that the CNC will use to machine your project.




Figure 1

Open VCarve Pro by double clicking on the icon (Figure 1).

You will be presented with a screen “Login or Register” (Figure 2). Choose Registered Member then click on “Next”.






Figure 2

In the following window one of two actions can be used to login to your Vectric account.

<p>Option 1: Enter your email account name in the window, then click on the bar “Send One Time Code”.</p>  <p>A code will be sent to your email account that can be entered, then choose “Next”.</p> <p>In the pop-up window choose “Finish”.</p>	<p>OR</p>	<p>Option 2: Choose “Login with Browser”.</p>  <p>You will then be presented with the Vectric Customer Login web page.</p> <p>Enter your email address and password associated with your Vectric account and then choose “Sign In”.</p>
---	-----------	---

You will then be presented with a window “Access Request” (Figure 3). Choose “Allow”.




Figure 3

Using Makerspace version of VCarve Pro at the Guild




Figure 4

You will then receive a window “Access Request Success” (Figure 4).

Minimize this window, you will need to close it after you generate the G-Code.

You will then receive a pop-up window stating “Congratulations you.....” (Figure 5). Choose “Finish”.




Figure 5

You are now into the Master Copy of VCarve Pro where you can open your existing file, fine tune your toolpaths and save the G-Code.

Signing out of VCarve Pro

After you have saved your G-Code and any changes you made to your design file you need to sign out of both VCarve Pro and the Vectric Web Page.




Figure 6

To sign out of VCarve Pro go to the “Help Menu” located at the top left of the program page.

Scroll down and choose “Makerspace Logout” (Figure 6). In the pop-up window choose “Logout”. If you receive a window “Login or Register” just exit it by choosing the “X” in the upper right of the popup.

To sign out of the Vectric Web Page Click on the browser icon at the bottom of the screen (Figure 7).




Figure 7




Figure 8

On the right side of the browser window click on “V&Co/Account” (Figure 8) and in the dropdown menu choose “Sign Out”.